

BS5837:2012 Tree Survey

Treestyle Consultancy Ltd

Client: Butterfield Architecture
 Project: 38 Whitelow Road
 Survey Date: 05/03/2022
 Surveyor: Andrew McLoughlin



Jepps Lane
 Barton
 Preston
 Lancashire
 PR3 5AQ
 Mobile: 07872064313

Tree and Tag No Species	Hght (m)	Stems		Crown		Age	RP A (m²) R (m)	Phys Condition	Structural Condition	Preliminary Recommendations			Cat ERC	
		No	Ø (mm)	Spread (m)	Clear (m)					Survey Comment				
G4												Estimated Measurements		
A Group	4	2	212 (Eq)	N	2	SM	A: 20.4	Good	C: Fair	No action :: Unspecified			B.2	
- -				E	2		R: 2.54		S: Fair				20 to 40 yrs	
				S	2				B: Good	Laurel with good screening				
				W	2									
H5												Estimated Measurements		
A Hedgerow	6	0		N	1	SM	A: 0	Fair	C: Fair	Prune :: Unspecified			B.2	
- <i>Spp.</i>				E	1		R: 0		S: Fair				10 to 20 yrs	
				S	1				B: Fair	Great screening, maintain as hedge				
				W	1									
H6												Estimated Measurements		
A Hedgerow	6	0		N	1	SM	A: 0	Fair	C: Fair	Prune :: Unspecified			B.2	
- <i>Spp.</i>				E	1		R: 0		S: Fair				10 to 20 yrs	
				S	1				B: Fair	Great screening, maintain as hedge				
				W	1									
T1												Estimated Measurements		
Sycamore	20	1	350	N	4	9	M	A: 55.4	Good	C: Fair	No action :: Unspecified			A.1
<i>Acer pseudoplatanus</i>				E	3	9		R: 4.19		S: Good				>40 yrs
				S	4	9				B: Fair	Located in neighbouring church, soil mounding			
				W	3	9								
Age Classifications:	N	Newly planted	EM	Early Mature		Condition:	C	Crown		Stems:	Ø	Diameter		
	Y	Young	M	Mature			S	Stem			(Eq)	Equivalent stem diameter using BS5837:2012 definition		
	SM	Semi-mature	OM	Over Mature			B	Basal area		ERC:		Estimated Remaining Contributio		

Tree and Tag No Species	Hght (m)	Stems		Crown		Age	RP A (m²) R (m)	Phys Condition	Structural Condition	Preliminary Recommendations		Cat ERC	
		No	Ø (mm)	Spread (m)	Clear (m)					Survey Comment			
T2											Estimated Measurements		
Leyland Cypress <i>X Cupressocyparis leylandii</i>	20	1	400	N	3	5	M	A: 72.4 R: 4.8	Fair	C: Fair S: Fair B: Good	No action :: Unspecified Neighbouring tree	B.1 10 to 20 yrs	
T3											Estimated Measurements		
Sycamore <i>Acer pseudoplatanus</i>	20	1	400	N	4	5	M	A: 72.4 R: 4.8	Good	C: Fair S: Good B: Fair	No action :: Unspecified Located in neighbouring land, suppressed form	B.1 10 to 20 yrs	
T7											Estimated Measurements		
Unknown - -	3	1	200	N	1		Dead	A: 18.1 R: 2.4	Dead	C: S: B:	Fell :: Unspecified Dead tree	U.2	
T8													
Downy Birch <i>Betula pubescens</i>	5	1	150	N	1	2		SM	A: 10.2 R: 1.8	Poor	C: Fair S: Poor B: Poor	Fell :: Fell to ground level Codominant specimen with above and below ground contraints and a mechanically weak structure.	U n/a
Age Classifications: N Newly planted EM Early Mature Condition: C Crown Stems: Ø Diameter Y Young M Mature S Stem (Eq) Equivalent stem diameter using BS5837:2012 definition SM Semi-mature OM Over Mature B Basal area ERC: Estimated Remaining Contributio													