© Layer Surveys Ltd. 2022
Reproduction in whole or in part by any means is prohibited without the prior permission of Layer Surveys Ltd.

N

PLAN GRID NORTH

File Name: Location/0001.dwf .dwg

## NOTES:

Survey Datum: Survey to OS (Heaven) Datum, Established using network RTK. Survey plotted on a plane Local Grid, Orientated to National Grid.

Services shown as 'From Statutory Authority Plans' line styles are taken from Statutory Records plans supplied by the relevant regional authority. These services were not located and are shown for indicative purposes only.

Please note survey control established for mapping only. Control should not be used by third parties without confirmation from Layer Surveys.

Tree Spreads are symbolic only and are representative of the average spread.

Only manholes and services visible at time of survey shown.

Drainage information must be checked and verified with local authority records prior to work commencing.

Please note all drainage information has be taken from CCTV condition survey. Drainage added to supplied topographical.

## LEGEND:

| | | | |
|---|---|---|---|
| AV | AIR VALVE | PP | PERCH POINT |
| BI | BI MARKING ON COVER | RP | RODDING EYE |
| CAB | CABINET | RSJ | RSJ MARKING |
| COM | COMMUNICATIONS | SCP | SCOUR POINT |
| CP | CAMERA PIT COVER | SV | SCOUR VALVE |
| CT | CABLE TV COVER | TB | TELEPHONE CALL BOX |
| DP | DRAINAGE POINT | TP | TELEPHONE POLE |
| EB | ELECTRIC BOX | TR | TELEPHONE PIT |
| EM | ELECTRIC MARKING | WA | WATER AIR VALVE |
| FH | FIRE HYDRANT | WH | WATER HEATER |
| GM | GAS MARKER | WM | WATER METER |
| GP | GAS PATCH POST | WO | WATER POST OFF KILT |
| GV | GAS VALVE | WP | WATER POST UP KILT |
| HL | HANDRAIL/GUARD RAIL | WV | WATER VALVE |
| IC | INSPECTION COVER | STW | STW ST TANK |
| LC | LAMP COVER | UC | UNKNOWN COVER |
| LP | LAMP POST | VC | VALVE COVER |
| MH | MANHOLE | WC | WATER COVER |
| MP | MARKER POST | WI | WATER INLET |
| OC | OPEN COVER | WT | WATER TROUGH |
| PC | PIPE COVER | | |

| | |
|---|---|
| BT | BT |
| CABLE TV | |
| ELEC | ELECTRIC |
| GAS | GAS |
| GAS DISTRIBUTION | |
| GAS MAIN | |
| GAS TRANSMISSION | |
| GAS TRANSMISSION LINE | |
| GAS VALVE | |
| MAIN WATER | |
| SEWER FM | |
| SEWER SW | |
| SEWER UNK | |
| TRAFFIC SIGNAL CABLE | |
| UNDERGROUND CABLE | |
| UNDERGROUND DUCT | |
| UNDERGROUND WIRE | |
| VEHICLE DETECTOR LOOP | |

Indicates MH Surface (S) or (B) Invert Statutory Authority Records and Recorded Underground Utility

## DISCLAIMER:

At Layer Surveys we use skilled and experienced staff, modern up to date equipment and the latest survey techniques and ground penetrating technology to locate and trace sub-surface utilities. However the performance of the equipment employed in non-invasive surveys can be affected by numerous factors, including ground and weather conditions. Therefore Layer Surveys cannot guarantee that all utilities present on site have been located. It is the responsibility of the Client to consult with the relevant utility companies and to agree the limits of responsibility.

Where similar services run in close proximity it may be impossible to separately trace individual services as the trace signal can experience cross-coupling from one service to another. Where this is suspected this line, the displayed depth will refer to the shallowest detected utility.

Successful tracing of non-conductive materials may be limited. Drainage gullies are also tested where possible to prove connectivity but it is not always possible to introduce the smoke due to narrow pipe sizes and/or blockages.

Depth information of underground services/features are generally accurate to within +/- 10% (i.e. a pipe at 2m deep may be accurate to between 1.8m and 2.2m). Greater accuracy can be obtained by excavation to the top of the service. Directly viewed and depth depths are usually to invert (base of drainage channel) unless otherwise stated.

Ground conditions may change in the period between the time of survey. It is not always possible to operate the Ground Penetrating Radar in areas including, but not limited to, dense vegetation, rubble, debris, standing water and fast flowing.

Adding to any information that was made available to Layer Surveys by the Client or by the statutory utility provider should be regarded only as an indication and cannot be guaranteed.

No condition in the vicinity of services shown should be carried out with 'due diligence (NAT SIGHT).

| REV | DATE | DESCRIPTION |
|---|---|---|

**LAYER SURVEYS LTD**
SEE THE COMPLETE PICTURE

Client
Casey
Rydings Road
Rochdale
OL12 9PS

Project Title
Glendene
Wythenshawe
Manchester
M23 2RE

| | | | |
|---|---|---|---|
| Drawing Ref. 1447 | | Surveyed J.C. | Checked Layer Surveys |
| Scale 1:200 | Date septembe 22 | Drawn LT | No. 01 / Size A0 / Rev - |