© Survey & Engineering Projects Ltd. 2022
Reproduction in whole or in part by any means is prohibited without the prior permission of Survey & Engineering Projects Ltd.
T. (01695) 729505 F. (01695) 720066 W. www.sepsurvey.com E. info@sepsurvey.com

N

PLAN GRID NORTH

File Name: S23925-U.dwg

LEGEND

AV	AIR VALVE	BT	BT-A / BT-A
BT	BT INSPECTION COVER	BT STAT RECORD	BT-A / BT-A
CB	CONTROL BOX	CABLE DUCT	DUCT-A / DUCT-A
CBT	CABLE TV MARKER POST		
COM	COMMUNICATIONS COVER	CABLE TV	CA-A / CA-A
CV	CABLE TV COVER	CABLE TV STAT RECORD	CA-A / CA-A
DM	DRAINAGE MANHOLE	DUCT	DUCT-A / DUCT-A
DP	DOWN PIPE	DUCT STAT RECORD	DUCT-A / DUCT-A
EB	ELEC BOX	TELECOMS	TC-O / TC-O
EIC	ELEC INSPECTION COVER	TELECOMS STAT RECORD	TC-O / TC-O
EM	ELEC METER	EARTH ROD STRIP	EARTH-A / EARTH-A
ER	EARTH ROD	ELECTRIC	EL-A / EL-A
EP	ELECTRICITY POLE	ELECTRIC STAT RECORD	EL-A / EL-A
FCL	FINISHED CARRIAGE LEVEL	FIBRE OPTICS	FI-A / FI-A
FH	FIRE HYDRANT	FIBRE OPTICS STAT RECORD	FI-A / FI-A
G	GULLY		
GLT	GROUND LIGHT	FUEL LINE	FL-A / FL-A
GST	GAS TAP	FUEL LINE STAT RECORD	FL-A / FL-A
GV	GAS VALVE	GAS MAIN LINE	GAS-M / GAS-M
IC	INSPECTION COVER	WATER MAIN	WM-S / WM-S
IL	INVERT LEVEL	WATER MAIN STAT RECORD	WM-S / WM-S
LP	LAMP POST	MAINS WATER	MW-A / MW-A
MH	MANHOLE	MAINS WATER STAT RECORD	MW-A / MW-A
MP	MARKER POST	SEWER CW	CW-A / CW-A
MW	MANWAY	SEWER CW STAT RECORD	CW-A / CW-A
OP	OUTFALL PIPE	SEWER FW	FW-A / FW-A
PC	PEDESTAL	SEWER FW STAT RECORD	FW-A / FW-A
PP	PETROL PUMP	SEWER SW	SW-A / SW-A
RE	RODDING EYE	SEWER SW STAT RECORD	SW-A / SW-A
SHP	SHOWER HEAD PIPE	TRAFFIC SIGNAL CABLE	TRAFFIC / TRAFFIC
SOF	SOFFIT LEVEL		
SV	STOP VALVE	UNIDENTIFIED TRACE	UT-A / UT-A
TCB	TELECOMS CALL BOX	UNIDENTIFIED DUCT	UDT-A / UDT-A
TL	TRAFFIC LIGHT	UNIDENTIFIED PIPE	UP-A / UP-A
TLB	TRAFFIC LIGHT BOX	VEHICLE DETECTOR CABLE	VEHICLE / VEHICLE
TP	TELEGRAPH POLE	WATER FEATURE	WATER / WATER
WM	WATER METER	SURVEY BOUNDARY	
WP	WATER POLE	OUTSIDE SURVEY AREA	
WST	WATER STOP TAP		
WSV	WATER STOP VALVE		
EOT	END OF TRACE	QUALITY LEVEL	
OSA	OUTSIDE SURVEY AREA	A – Verification	
UTL	UNABLE TO LIFT	B1 – Horizontal/Vertical location using multiple techniques	
UTS	UNABLE TO SONDE		
UTT	UNABLE TO TRACE	B2 – Horizontal/Vertical location using a single technique	
SLS	SIGNAL LOSS		
BLK	BLOCKED	B3 – Horizontal location using a single technique	
NCP	NO CONCRETE CAP OVER CONTACTS		
BG	BACKDROP GRID	B4 – Assumed route	
TOC	TOP OF CABLE		
TOP	TOP OF PIPE	C – Site Reconnaissance	
TOS	TOP OF SLAB		
FR	FITTING FROM RECORDS	D – Desktop utility records search	

NOTES:

All levels relate to O.S (Newlyn) Datum, Established using network RTK. Survey plotted on a plane local grid, orientated to National Grid.

This Underground Utilities survey was conducted in compliance with the BSI PAS128:2014 standards.
Services linetypes display text indicating first an abbreviation of the services' type, followed by a hyphen, then followed by the Quality Level to which that service was located (eg. E4 = Assumed route).

Quality Level descriptions shown in the above legend are for reference purposes only and are not intended as detailed descriptions.
For more information on Quality Levels please consult the
BSI PAS 128:2014 standards document.

Lines annotated as GPR indicate a series of consistent subsurface anomalies located using the Ground Penetrating Radar and should be considered as Quality Level B3. The nature of these anomalies could not be determine by non-invasive means. GPR lines that were identifiable as a service are shown as their respective service.

DISCLAIMER:

All SEP we use skilled and experienced staff, modern up to date techniques and top of the range electromagnetic and radar technology to locate and trace sub-surface utilities. However the performance of the equipment employed in non-invasive surveys can be adversely affected by factors outside the control of SEP. Therefore SEP cannot guarantee that all utilities present on site have been located. It is the responsibility of the Client to consult regional authority records and undertake trial digs where appropriate.

Where similar services run in close proximity it may be impossible to separately trace individual services as the trace signal can experience interference. In such cases, services will be shown as a single, annotated line. The displayed depth will refer to the shallowest detected utility.

Successful tracing of non-conductive materials may be limited. Drainage gullies are rule tested where possible to prove connectivity but if it not always possible to introduce the sonde due to narrow pipe sizes and/or accumulated silt.

Depth information of underground services/features are generally accurate to within +/- 10% (i.e. a pipe at 2m deep may be accurate to +/-200mm) but this cannot be guaranteed. Depths shown usually refer to the top of the service. Gravity sewer and drain depths are usually to invert (base of drainage channel) unless otherwise stated.

Some above ground features may have been obscured at time of survey. If is not always possible to operate the Ground Penetrating Radar in areas including, but not limited to, dense vegetation, rubble, debris and/or rough/uneven ground.

Existing record information that was made available to SEP by the Client or by the statutory utility provider should be regarded only as an indication and cannot be guaranteed.

Excavation in the vicinity of services shown should be carried out with due diligence (Ref. HSG47).

0 2m 4m 8m 12m 16m
SCALE BAR

REV	DATE	DESCRIPTION

SURVEY & ENGINEERING PROJECTS

Client
Morgan Sindall Construction & Infrastructure Ltd
6th Floor
2 Anchorage Quays
Salford
Manchester
M50 3YW

Project Title
Utility Survey of Land at:
Library Site
Gorton Community Hub
Garratt Way
Gorton
Manchester, M18 8LD

Surveyed	Drawn	Checked
D.Protheroe	D.Shipton	J.Gardner

Scale	Date	Drawing Ref.	No.	Size	Rev
1:200	Oct 22	S23925-U	01	A0	--