



Plate 1: General shot of building showing corner of Mosley Street and York Street



Plate 2: Southern end of elevation showing bays 1 - 4



Plate 3: Ground and first floor detail of above



Plate 4: Second and third floor details



Plate 5: Second floor window detail



Plate 6: Bay 1 detail showing former doorway



Plate 7: Main entrance to bay 5



Plate 8: Recessed second and third floors at bay 5




Plate 9: Bays 6 – 12 showing the original building



Plate 10: Ground and first floor window detail



Plate 11: Second and third floor windows



Plate 12: Bays 6 – 12



Plate 13: Second floor windows showing differing central window



Plate 14: Elevation to York Street



Plate 15: As above from West Mosley Street



Plate 16: Doorway in bay 6



Plate 17: Elevation to West Mosley Street



Plate 18: Bay 1 shown above



Plate 19: Bays 2 – 4 with rounded face and recessed brick section above




Plate 20: Detail of ground and first floors



Plate 21: Detail of second and third floors



Plate 22: Bays 5 - 8



Plate 23: Ground floor detail



Plate 24: Upper floor windows in bays 5 and 6



Plate 25: Bays 5 – 8 looking north



Plate 26: Bays 9 - 12

Ground Floor



Plate 27: Southern Room showing windows to Mosley Street



Plate 28: Room to the north of the above, showing offices close to lifts



Plate 29: Inserted lifts



Plate 30: Interior of main entrance showing sliding door



Plate 31: Main banking hall



Plate 32: As above



Plate 33: Panelling detail on timber at base of wall and base of columns



Plate 34: Window details



Plate 35: Ceiling detail



Plate 36: Banking hall looking towards the corner of York Street and West Mosley Street



Plate 37: Curved wall to West Mosley Street



Plate 38: Goods lift to basement



Plate 39: Staircase in northwest corner of building



Plate 40: Room to south of curved wall



Plate 41: As above showing cornice



Plate 42: Corridor along west end of the building, running south



Plate 43: Store room in northern end of extension



Plate 44: Large room towards southern end of extension

First Floor



Plate 45: Southern room of extension facing Mosley Street



Plate 46: Stripped out WC no north end of extension



Plate 47: Wall of bay 5 to Mosley Street showing mechanism for opening the sliding doorway below



Plate 48: Inserted lift block



Plate 49: Corridor to northwest corner of extension



Plate 50: Inserted kitchen in first floor of original building



Plate 51: Detail of ceiling showing cornice in room shown above



Plate 52: Room to southwest corner of extension



Plate 53: Detail of concrete ceiling construction throughout extension

Second Floor



Plate 54: Staircase in southwest corner of original building



Plate 55: Open area to southeast corner of extension showing windows to Mosley Street



Plate 56: Recessed second floor to bay 5 showing large window



Plate 57: Subdivided room to south end of original building



Plate 58: Windows to Mosley Steet in south end of original building



Plate 59: Room as above showing doorway to main central office room



Plate 60: Main central office



Plate 61: Ceiling detail



Plate 62: Doorway detail



Plate 63: Northern room of original building



Plate 64: eastern end showing cornice



Plate 65: General shot of room



Plate 66: Detail of damaged cornice



Plate 67: Staircase at northwest corner of building



Plate 68: Western corridor linking office rooms



Plate 69: Doorway to main central office detail



Plate 70: General shot of corridor looking north



Plate 71: WC to west side of original building



Plate 72: Continuation of corridor shown above to the south, into extension




Plate 73: Detail of ceiling showing damaged cornice in corridor above



Plate 74: WC off corridor above showing cornice



Plate 75: Inserted lift bank to extension



Plate 76: Room to northwest corner of extension



Plate 77: Room to southwest corner of extension

Third floor



Plate 78: Room to southeast corner of extension



Plate 79: Room above bay 5 to Mosley Street showing large window



Plate 80: Detail of concrete ceiling construction



Plate 81: Sandstone lintel of former external window of original building



Plate 82: Room to southeast corner of original building



Plate 83: Detail of visible window lintel in former external wall



Plate 84: General shot of room shown above



Plate 85: Office to east side



Plate 86: Corridor linking inserted offices to east side



Plate 87: Detail of office window showing surround



Plate 88: Ceiling detail of inserted office, showing cornice



Plate 89: Large open space to north side of original building



Plate 90: As above



Plate 91: Ceiling detail of room above showing cornice indicating former corridor



Plate 92: General shot of room shown above



Plate 93: Metal staircase to roof access



Plate 94: Corridor to west end of original building



Plate 95: Staircase in northwest corner



Plate 96: Corridor continuing south from corridor shown above



Plate 97: Stripped out WC in southwest corner of original building

Basement



Plate 98: Corridor in southwest corner of original building looking north



Plate 99: Corridor into rooms below arched wall area



Plate 100: Arched wall with alcove



Plate 101: Corridor into vault area



Plate 102: Northern vault area of original building



Plate 103: Staircase in northwest corner



Plate 104: Northern area of original building



Plate 105: As above showing vault door



Plate 106: Further vault door



Plate 107 as above showing arched ceiling



Plate 108: Central room of original building showing inserted wall and plasterboard ceiling



Plate 109: Eastern end of room shown above



Plate 110: Southern room of original building



Plate 111: Room to northeast corner of extension



Plate 112: As above showing decaying plasterwork



Plate 113: Detail of glazed bricks



Plate 114: Corridor to west end of extension



Plate 115: Glazed brick behind plasterboard in room to southeast corner of extension



Plate 116: Inserted kitchen to southwest end of extension