



Existing joists cut at the centreline of the existing primary beam. This allows for future reinstatement of these joists. Cutting at this point will hide any cut lines from view following reinstatement of the joists



Existing pocket in wall to be cleaned and retained indicating previous joist location and allowing for future reinstatement of joist



CURRENT CONDITION

AS OF AUGUST 2022

FOR INFORMATION	-
DRAWING No. 00028-SK-001 - SEQUENCING	REV P01