

HighWays Dilapidation Survey

C1821

Monday, 25 July 2022

39 Issues Identified

A handwritten signature in black ink, appearing to read 'D. Monaghan'.


D. Monaghan

ADT




Issue 1

Bootle street right hand side of roller shutter pavement cracked.



Issue 2

Bootle street/corner posts to roller shutter marked and scuffed.




Issue 3

Bootle street/ drain and road damaged afacing roller shutter



Issue 4

Bootle street manhole cover damaged around the pavement...



Issue 5

Bootle street / pavement defects In various places..




Issue 6

Bootle street / box damaged & marked in various places...



Issue 7

Bootle street/pavement damaged various places.



Issue 8

Peter street/pavement cracked & damaged in various places outside main entrance.



Issue 9

Peter street / pavement cracked on footpath and kerbs



Issue 10

Peter street/ right hand side column chipped various places...



Issue 11

37 Peter street / pavement damaged in various places.




Issue 12

37 Peter street / pavement



Issue 13

37 Peter street/ pavement damages in front of building.




Issue 14

37 Peter street / pavement damages outside building




Issue 15

Peter street / left hand side/single entrance door disfigured stone work




Issue 16

Peter street single entrance right hand side column disfigured and damaged stone work



Issue 17

37 Peter street pavement damages outside entrance single door.



Issue 18

37 Peter street / pavement cracked and damaged corner of Southmill Street.



Issue 19

37 Peter street / window left hand side disfigured stonework.




Issue 20

37 Peter street/ main entrance column cracked on stonework....




Issue 21

37 Peter street / pavement and kerb damaged..



Issue 22

37 Peter street / pavement stone cracked.



Issue 23

37 Peter street / step damaged to entrance



Issue 24

South mill Street / damages around manhole covers




Issue 25

Southmill Street/ Peter street damaged wall




Issue 26

South mill Street Medlock cabins



Issue 27

South mill Street Medlock compound



Issue 28

Bootle street Medlock compound tied herris fencing to building




Issue 29

Medlock cabins southmill Street




Issue 30

Medlock cabins southmill Street



Issue 31

Pavement corner of Southmill Street to Peter street damages to paving slabs and kerb.
..



Issue 32

37 Peter street paving slabs cracked and damaged in various places ...




Issue 33

Peter street pavement




Issue 34

37 Peter street cover damaged outside building.




Issue 35

37 Peter street various marks and damages in kerbs and paving slabs...




Issue 36

Peter street damages on footpath



Issue 37

Southmill Street/Peter street damages on footpath



Issue 38

Southmill Street/Peter street damages around manhole covers.

Issue 39

Southmill Street has Medlock cabins and compound situated on it.
So a condition survey can not be done to determine any damages to the pavement & road...
