





DISCLAIMER :
SURVEY BASED ON VISUAL INSPECTION OF SURFACE GROWTH. JKSL HOLD NO
LIABILITY FOR AREAS NOT IDENTIFIED IN INITIAL INVESTIGATION WORKS.
CONTINUED MONITORING OF SITE IS RECOMMENDED

-  SURVEY BOUNDARY
-  AREA OF JAPANESE KNOTWEED
-  7M RISK ZONE
-  EXCAVATION AREA
-  VERTICAL ROOT BARRIER




SURVEY ORIENTATED TO MAGNETIC NORTH

Rev	Description	Date	By	Chk
-----	-------------	------	----	-----

Client
Mace Group

Contract
Project RED, Manchester Royal Infirmary, North Manchester
General Hospital, Grafton St, Manchester, M13 9NT

Drawing
Japanese knotweed Excavation Extents



Japanese Knotweed
Solutions

UK'S LEADING JAPANESE KNOTWEED REMEDIATION SPECIALISTS

Workshops **T**reatment **E**mergency
Evaluation **R**emediation **R**esearch

UK'S LEADING JAPANESE KNOTWEED REMEDIATION SPECIALISTS

Drawing No.	JK21-7735-02	Revision	/
Scales	NTS	Date	07/12/2021
Drawn	KH	Checked	AD