


Photographs of Sample Panel Remedial Works – North Manchester General Hospital (June 2022)


Sample Panel




35mm Cover Flashing



50mm Cover Flashing



70mm Cover Flashing



50mm Door Window Flashing



Level 01 Flashing Detail

