
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 7

Defect Survey


Defect Survey Sheet



- Repairs
- Cracks

Zone 7 Defect Survey

Kim Brown Street



CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Photo References










6


6a


7


8


9


10


11


14


15


16


13
12


17


18


19



20


21


22


23


24


25


26


27


28


29


30


31


33


32


34


35


36


37


38


39


40


41


42


43


44


45


46


48
47