7th and 8th Floor, Sunlight House, Manchester

Photographic Schedule – As Existing



Photograph 1 – Existing Entrance (Door from Lift Lobby)



Photograph 2 – Existing Lights on Office Floor



Photograph 3 – Existing CO2+Temp Monitor



Photograph 4 – Existing CO2 Monitor



Photograph 5 – Existing Open Area



Photograph 6 – Existing Open Area

7th and 8th Floor, Sunlight House, Manchester

Photographic Schedule – As Existing



Photograph 7 – External Windows



Photograph 8 – External Windows



Photograph 9 – Electrical Cupboard on 7th Floor




Photograph 10 – Electrical Cupboard on 7th Floor

7th and 8th Floor, Sunlight House, Manchester

Photographic Schedule – As Existing



Photograph 11 – Stairs Landlord Area (Between 7 and 8)



Photograph 12 – Opening into the WC area



Photograph 13 – Level 8 Central Bulkhead



Photograph 14 – Level 8 Bulk Heads

7th and 8th Floor, Sunlight House, Manchester

Photographic Schedule – As Existing

	
Photograph 14 – Ceiling Mounted Smoke Detector	*Photograph 15 – Fire Exit Door & Alarm*