
CRL
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 8

Defect Survey


CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Defect Survey Sheet




Zone & Defect Survey

Brown Street



King Street return



Chancery Lane return

CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Photo References










5


6


8
7


9


10


11


12


13


14


15


16


17


18


19


20


21


22


23



24


25


26


27


28


29
30


31


32


33


34


35



36


37


38


39



40


41


42


43


44
45


48
47
46


49


50


51


53
52


54


55


56


57


59
58


60


61


62