

**Parapet wall on east side of
roof WCR02 repairs to
brickwork**

Page 1 of 3

Remove remnants of
lead flashing

Lintel to be cut
from stone
reclaimed from
elsewhere on site

580

170

1

3

300

2

4

Chute opening
300mm wide x 2
brick high

5

6

7

8

9

10

11

12

13

14

15

Fill all holes

Brickwork replaced
with new and
reclaimed brick to
reinstate Flemish bond

Repoint entire wall

16

Revision: -
Date: 14 March 2024

OTH-PUR-TH-RF-SKE-A-3524

**Parapet wall on east side of
roof WCR02 repairs to
brickwork**

Page 2 of 3

Remove remnants of
lead flashing

Repoint entire wall

Fill all holes

Fill all holes

17


Lead flashing line

Revision: -
Date: 14 March 2024

OTH-PUR-TH-RF-SKE-A-3524

Parapet wall on east side of
roof WCR02 repairs to
brickwork

Page 3 of 3



Remove remnants of
lead flashing

Fill all holes

Repoint entire wall

Lead flashing line

Fill all holes

Revision: -
Date: 14 March 2024