

Store Street Aqueduct – Leakage into 3rd Party Works (July 2025).

Site Inspector photos



Water inundation from area of aqueduct wing wall and embankment





Water leak through augured piles