
Echo St, Manchester [Chandos House]

SuDS - Photographic Evidence of Construction, Verification Report - Rev A

1. Rain Water Outlets & Waterproof Membrane installed



2. Blue roof storage crates installed



3. Breather membrane / fleece layer installed



4. Finishings installed




5. Above Ground Drainage - Surface Water Pipes installed







6. Below Ground Drainage (Manholes, inspection chambers, pipe runs)















7. Hydro brake to Surface Water System





