WinCan

Project

Project Name:	HAMMERSTONE ROAD GORTON_2
Project Date:	27/05/2026
Inspection Standard:	MSCC5 Sewers & Drainage GB (SRM5 Scoring)

WinCan

Table of Contents

Project Name	Project Number	Project Date
HAMMERSTONE ROAD GORTON_2		27/05/2026

Project Information P-1

Section Item 1: SRH08 > MHS29/EX06 (SRH08X) 1

Section Item 2: UPSTREAM > SRH08 (UPSTREAMY) 2

WinCan

Project Information

Project Name	Project Number	Project Date
HAMMERSTONE ROAD GORTON_2		27/05/2026

WinCan

Section Inspection - 27/05/2026 - SRH08X

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
1	1	27/05/26	16:40	Not Specified	Not Specified	Not Specified	SRH08X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	Not Specified	Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		**Inspection Direction:**	Downstream	**Upstream Node:**	SRH08
Road:		**Inspected Length:**	7.73 m	**Upstream Pipe Depth:**	
Location:		**Total Length:**	7.73 m	**Downstream Node:**	MHS29/EX06
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:		**Dia/Height:**	750 mm
Flow Control:		**Material:**	Concrete
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:		**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:67

Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m					
SRH08					
0.00	MH	Start node, manhole, reference: SRH08			
7.73	MHF	Finish node, manhole, reference: MHS29/EX06			
MHS29/EX06					
Depth: m					

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

WinCan

Section Inspection - 27/05/2026 - UPSTREAMY

Item No.	Insp. No.	Date	Time	Client`s Job Ref	Weather	Pre Cleaned	PLR
2	1	27/05/26	16:43	Not Specified	Not Specified	Not Specified	UPSTREAMY


Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	Not Specified	Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		**Inspection Direction:**	Upstream	**Upstream Node:**	UPSTREAM
Road:		**Inspected Length:**	30.36 m	**Upstream Pipe Depth:**	
Location:		**Total Length:**	30.36 m	**Downstream Node:**	SRH08
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Surface water	**Pipe Shape:**	Circular
Type of Pipe:		**Dia/Height:**	750 mm
Flow Control:		**Material:**	Concrete
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:		**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:263	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m SRH08						
	0.00	MH	Start node, manhole, reference: SRH08			



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0