D:\Rigg Tech\Reports\Lancaster 80 - Manchester\2020 inspection\Documents\Defect plots rev 2.dwg

RAG Legend

- (R) High risk of failure & high potential risk of serious injury to public.
- (A) danger of detachment and risk to public.
- (G) Requires planned repair. Low risk to public.
- Cracking

Drawing to be read in conjunction with defect schedules.

P13 W1 W2 W3 W4 W5 W6 W7 W8 W9 W10 W11 W12 W13 W14 W15 W16 W17 W18 W19

Cupola & dome | Central tower | Lower tower | Roof level | Floor 7 | Floor 6 | Floor 5 | Floor 4 | Floor 3 | Floor 2 | Floor 1 | Ground floor | Basement

+46.54m +44.35m +43.33m +39.09m +38.61m +19.07m +9.31m +8.93m

WHITWORTH STREET ELEVATION

20m 10m 8m 6m 4m 2m 0

RevNo	Revision note	Date	Signature	Checked

Article No./Reference	Scale do not scale	Sheet 1/1
Title/Name, designation, material, dimension etc	Date 07.09.2020	Edition A
Checked by	File name 003	Approved by - date
Quantity	Designed by N. M	Itemref

Whitworth Street elevation defect plot

Lancaster 80, Manchester

A3

RIGG TECH Ltd
Unit E3 Springfield Industrial Estate, Samual Street,
Manchester, M35 0GA. Tel: 0161 684 7800
E-mail: info@rigg-tech.com Web: www.rigg-tech.com