Heaton Park Farm

95.4m

MH10

UTR

ASTRO

MH9

MH8

ASTRO

MH7 (Blocked)

MH3

MH5

UTR

MH2

MH6

Grease Trap

Disabled Toilet

Pipe @ 0.3c Compressed

AC01

MH1 (SA)

MH11

MH4

Carpark

SA @ 22.4c

Carpark Off.

UTR = UNABLE TO RAISE

UTL = UNABLE TO LOCATE

MH6 = GREASE TRAP

General Utilities Northwest Limited
Unit 1, Boundary Trading Park,
Liverpool Road, Irlam, Manchester M44 6FB
tel: 0161 776 0011 fax: 0161 776 0044
email: generalutilities@btconnect.com