

Health & Safety File

CDM Regulations 2015



Project Name: B1515 Angel Square

Date: 03 March 2025

Version: 1

Issue Date	Version	Review Date	Author	Owner	Page
23/10/18	5.0	23/10/21	D ROACH	BETHELL	Page 1 of 22
Review Date is 2 years from Issue Date			Retention Period is 5 years from Review Date		

Health & Safety File

Contents

	Page No.
1 Guidance on the use of the Health & Safety File Summary Report	3
2 Asset Development Record	3
3 Residual Hazards	4
3.1 Ground	4
3.2 Asbestos	5
3.3 Legionella	5
3.4 Fire	5
3.5 Confined Spaces	5
3.6 Explosive Atmospheres	6
3.7 Chemicals	6
3.8 Other Hazardous Areas	6
4 Key Structural Design Principles	7
4.1 Structural Design Information	7/8
4.2 Floor / Roof Loadings and Restrictions	8
5 Material Hazards	9
6 Removal / Dismantling of Structures, Installed Plant and/or Equipment	10
7 Cleaning / Maintenance	11/13
8 Services	14
9 Drawings & Other Information	15
9.1 Other Information	15
9.2 Drawings	15

Health & Safety File

1. Guidance on the use of the Health & Safety File Summary Report

This Health & Safety File Summary Report has been compiled in line with the requirements described under the Construction (Design and Management) Regulations 2015.

Where alterations to the asset are to be undertaken, this document will provide assistance. However, professional advice should be sought before, for example, forming holes, loading structures more heavily than previously or where there is any doubt.

2. Asset Development Record

This section provides summary details of completed projects related to the asset. It is intended that details of any future projects shall be added into this section, to provide a full and on-going record of the development of the asset.

Project Title:	Angel Square, Manchester	
UU Project No:		
Start Date:	24 February 2025	
Completion Date:	28 February 2025	
Summary Description of Project Works:	Construction of new 1200mm dia chamber with 4nr 150mm dia incoming line and 1nr 150mm dia outfall line, with new D400 cover and frame.	
Client:	Name: Address: Contact Name: Title: Tel:	NOMA Ltd C/O Brodies LLP Capital Square, 58 Morrison St, Edinburgh EH3 8EP Jon Grafton 07552 169205
Clients Representative (if applicable):	Name: Address: Contact Name: Title: Tel:	Gardiner and Theobald, 17-19 Whitworth Street Manchester M1 5WG Michael Martin 07909 254892
Principal Designer:	Name: Address: Contact Name: Title: Tel:	Buro Happold

Health & Safety File

Principal Contractor:	Name: Bethell Construction Ltd Address: Contact Name: James Eccles Title: MANAGER Tel: 07790 976968
Contractor:	Name: N/A Address: Contact Name: Title: Tel:

3. Residual Hazards

No special residual hazards other than those associated with a combined sewer system manhole within the works

3.1 Ground: n/a

3.2 Asbestos: n/a

None Encountered

3.3 Legionella:

N/A

3.4 Fire:

3.4.1 Historical finds.

None Encountered within the excavations carried out on site

3.5 Confined Spaces:

As per standard classifications for combined manholes

On site trained teams and SSOW implemented for manhole entry

3.6 Explosive Atmospheres:

None Created

3.7 Chemicals:

N/A

3.8 Other Hazardous Areas:

NON-FOUND

4. Key Structural Design Principles

4.1 Structural Design Information


a) n/a

e) Design Documentation



- Chamber Rings	DN1200x500	FP McCann
- Cover Slab	DN1200	FP McCann
- PCC Seating Rings	600 x 600mm	Elite PreCast
- Polysewer Pipes and Couplers	All Sizes	PolyPipe
- Cement		Cemex
- Gen3 Ready Mixed Concrete		Breedon

Health & Safety File



Point A – End of Downstream Pipe	384389.852,399028.895	42.510	Angel Square, Manchester
Point B – Chamber SW11 (Invert)	384393.887,399031.675	42.606	
(Cover Level)		44.227	Surveyed 28Feb2025
Point C – end of Upstream Pipe	384395.456,399029.324	43.386	NOT TO SCALE

4.2 Floor / Roof Loadings and Restrictions

N/A

5. Material Hazards

The following hazardous material/substances have been identified as part of the construction process:

No residual hazards from materials used.

5.1 Historical finds.

No works of significance were encountered within the excavations carried out on site therefore no requirement for archaeological involvement.

6. Removal / Dismantling of Structures, Installed Plant and/or Equipment

N/A

7. Cleaning / Maintenance

n/a

8. Services

n/a

Health & Safety File

9. Drawings & Other Information

As per below photos.



Health & Safety File



Health & Safety File



Health & Safety File



Health & Safety File





Health & Safety File







Health & Safety File



Health & Safety File



Health & Safety File



Health & Safety File



Health & Safety File



Health & Safety File



Health & Safety File