LOCATION OF COMPLIANT BATHROOM WALL WOULD ENCROACH INTO WINDOW IF CHIMNEY BREAST WAS TO RETAINED

EXISTING CHIMNEY BREAST STRUCTURE

udio

Acc. Studio

Original chimney breast uncovered during demolition, required to be removed to facilitate compliant accessible bedrooms

1000 x1500

Lobby

Lobby